










6 EXISTING STOREFRONTS
SCALE:N.T.S.



SOURCE: MONTCLAIR PLANNING DEPARTMENT



PARAPET BRICK DETAIL


SCALE: N.T.S.

5 DAMAGED CENTRAL COLUMN SCALE:N.T.S.



PARAPET BRICK DETAIL


SCALE:N.T.S.



WATERPROOF RECEPTACLE OUTLET GROUND FAULT INTERRUPTER OUTLET SPLIT WIRED RECEPTACLE OUTLET THREE WAY SWITCH FOUR WAY SWITCH DIMMER SWITCH FAN CONTROLLER SWITCH W/ INDICATOR LIGHT CABLE TV JACK

TELEPHONE OR DATA JACK DOOR CHIME BUTTON BELL, CHIME OR BUZZER L.E.D. LIGHT FIXTURE-SURFACE MOUNT L.E.D. LIGHT FIXTURE-WALL MOUNT L.E.D. LIGHT FIXTURE-RECESSED L.E.D. OR INCAND. LIGHT FIXTURE-W/ SWITCH OR PULL CHAIN

CEILING FAN, VERSION W/ LIGHTS SHOWN FLOOR DRAIN MEDICINE CABINET



NEW NON-RATED UNINSULATED FRAMED CONSTRUCTION, SEE WALL TYPES SCHEDULE NEW 2-HOUR RATED FRAMED CONSTRUCTION, SEE WALL TYPES SCHEDULE. NEW BRICK CONSTRUCTION, SEE WALL TYPES SCHEDULE.

NEW CONCRETE BLOCK CONSTRUCTION, SEE WALL TYPES SCHEDULE.

NEW POURED CONCRETE CONSTRUCTION, SEE WALL TYPES SCHEDULE.

EXISTING CONSTRUCTION, TO REMAIN, V.I.F. EXISTING CONSTRUCTION, TO BE REMOVED, V.I.F.

PROJECT INFORMATION

SITE LOCATION: 330-346 Bloomfield Avenue, Montclair, New Jersey 07042

OWNER: 330 Bloom, LLC NATURE OF APPLICATION: The subject property includes two buildings. This application's primary focus is the easterly building, 330-334 Bloomfield Avenue. This building is a 3-story brick edifice, circa 1900, with a full basement, containing retail spaces on the ground floor and apartments on the upper floors. Unfortunately, the existing facade is in very poor condition. It is leaking in several areas, is cracking in many others, and the parapet is overturning. Several lintels and a major storefront column are severely damaged.

This project proposes removing the existing face brick, retaining and stabilizing the inner wythes of masonry, and then installing new face brick to match what is currently there.

The entire parapet will be taken apart and rebuilt to match the original design exactly. The building currently has vinyl windows which are aging poorly; they will be replaced with new clad wood windows. Existing limestone elements will be salvaged and stockpiled for re-use to the greatest extent possible. The existing storefront bulkhead walls are covered in rough stucco; they will be replaced with historically-correct panels built out of wood or similar composite material.

The westerly building on the plot, the 2-story tall 334-346 Bloomfield Avenue, is in much better condition. We propose basic repainting, re-pointing, and flashing replacement there as required.


4. USE GROUP M, B, \$ R-2 CONSTRUCTION TYPE: III-B
5. BLOCK: 3104 LOT: 21

DRAWING LIST:

PROPERTY SURVEY, AREA MAP, EXISTING PHOTOGRAPHS, PROJECT INFO

PROPOSED WORK

EXISTING CONDITIONS





LINEAR L.E.D. OR FLUORESCENT LIGHT FIXTURE FLOOD LAMP HOLDER EXHAUST FAN-DUCT TO EXTERIOR ILLUMINATED EXIT LIGHT FIXTURE I-I/2 HR BATTERY BACK-UP EMERGENCY LIGHT FIXTURE

I-I/2 HR BATTERY BACK-UP SMOKE DETECTOR-HARD WIRED-BATTERY BACK-UP-INTERCONNECTED STROBE/HORN FIRE ALARM

> CARBON MONOXIDE DETECTOR-HARD WIRED-BATTERY BACK-UP-INTERCONNECTED NATURAL GAS OUTLET W/ SHUTOFF HOSE BIB-FROST PROOF

THERMOSTAT HVAC RETURN REGISTER HVAC SUPPLY REGISTER FIRE DAMPER - PROVIDE ACCESS TO RESET RADIATOR TOE KICK RADIATOR

> ROLL-DOWN FIRE SHUTTER MAGNETIC DOOR HOLD-OPEN

SOUND SYSTEM SPEAKER OUTLET

KEYPAD

EXISTING CONSTRUCTION, TO REMAIN, V.I.F.
(PLAN)

PROPERTY SURVEY

SURVEY PREPARED ON 07-20-2017 BY: ALAN R. BOETTGER, P.L.S. OF CLEARPOINT SERVICES, LLC 2105 W. COUNTY LINE RD, STE. 8 JACKSON, NJ 08527 TELEPHONE: (732) 905-5463

APPROVAL SIGNATURES & DATES DATE: TOWNSHIP BOARD CHAIR TOWNSHIP BOARD SECRETARY DATE: TOWNSHIP ENGINEER DATE:

SHEET NO.

3 OF 3

EXISTING LINTEL

SCALE:N.T.S.

8 EXISTING PARAPET SCALE:N.T.S.

